

In Figure 1, the cross-brace 3c has been identified.

In Figure 2, connecting lines have been added for elements 2, 3 and 4.

In Figure 3, bottom left, the element 11/12 has been indicated.

In Figure 4, a connecting line has been added for element 4.

In Figure 5, a connecting line has been added for element 64 and slider joint 61a, groove 63a and pin joint 63b have been identified.

In Figure 6, hub assembly 40 and hub case 41 have been identified and notch 52 has been added. Specific support for the notch can be found on page 9, line 18.

Thus, no new matter has been entered by any of these amendments.

Respectfully submitted,

BELL, BOYD & LLOYD

By: Dante J. Picciano
Dante J. Picciano
Reg. No. 33,543

BELL, BOYD & LLOYD
P.O. Box 1135
Chicago, IL 60690-1135